

SECRET
CENTRAL INTELLIGENCE AGENCY

- 2 -

25X1

25X1

- 9 - Electric furnaces producing quicklime
- 10 - Sawmills
- 11 - Electrical and gas regulators for controlling blast furnace temperatures.
- 12 - Scrap iron dump and crane (not shown on plan).
- 13 - Electric generators (not shown on plan)
- 14 - Earthenware baths for the "Ingus-forme" models, dimensions 1 m. x 20 cms., sunk two meters in the ground. Siemens Martin blast furnaces.
- 15 - Electric generators for the Siemens Martin furnaces
- 16 - Foundry
- 17 - Electric furnaces
- 18 - Electric furnaces
- 19 - Electric generators for the rolling mill section (not shown on plan).
- 20 - Hot rolling mills
- 21 - Blacksmith shop
- 21a - Gas generators
- 22 - Forge furnaces
- 23 - Steel cutting department
- 24 - Main furnaces
- 25 - Electro-technical workshop
- 26 - De-rusting section
- 27 - Cold rolling section
- 28 - Barbed wire section
- 29 - Large warehouses (not shown on plan)
- 30 - Chemical laboratory
- 31 - Fireguards
- 32 - Nail department
- 33 - Smithy and carpentry department (not shown on plan)
- 34 - Mechanical workshops
- 35 - Construction section
- 36 - Secondary furnaces
- 37 - Zinc products section
- 38 - Tubing department
- 39 - Welding

25X1

CONFIDENTIAL

CENTRAL INTELLIGENCE AGENCY

- 3 -

25X1

25X1

- 40 -- Boiler section
- 41 -- Workers cooperative store
- 42 -- Entrance No. 2
- 43 -- Brick furnaces
- 44 -- Railroad section
- 45 -- Railroad administration
- 46 -- Main dump (not shown on plan)
- 47 -- Large mobile crane over railroad sidings
- 48 -- Installation workshops

CONFIDENTIAL

25X1